

## Preventing Falls Together – Project Summary

Project Name: New Lighting at Wentworth United Church

Developing Coalition: Cumberland County

Project Summary:

Two projects were recently undertaken to improve walking conditions at Wentworth United Church. New lighting was installed in dark areas of the main stairs, and the cement steps at the back entrance were smoothed and freed of cracks and crevices.

PFT Staff Contact:

Brenda MacKinnon

Central NS Field Worker

[nscentral@preventingfallstogether.ca](mailto:nscentral@preventingfallstogether.ca)